



Model: W618/1

Basic size of
mm


d:	1
D:	3
B:	1

The basic rated load is
kN

trends C:	0.056
static state Co:	0.017
Fatigue load limit Pu:	0.00075

Rated rotation speed is
r/min

Refer to the speed:	240000
limit speed:	150000
Mass kg:	0.000036
model:	W618/1



Dimensions are
mm

d:	1
d1 ~ :	1.6
D1 ~ :	2.4
r1,2 the min:	0.05

Shoulder gear and chamfer size
mm

d_a the min:	1.4
D_a the max:	2.6
r_a the max:	0.05

Calculation coefficient

k_r:	0.015
f_o:	10