



Model: W618/4

Basic size of

mm

d: 4
D: 9
B: 2.

The basic rated load is

kN

trends C:	0.449
static state Co:	0.173
Fatigue load limit Pu:	0.0075

Rated rotation speed is
r/min

Refer to the speed:	140000
limit speed:	85000
Mass kg:	0.0007
model:	W618/4

Dimensions are
mm

d:	4
d1 ~ :	5.
D1 ~ :	7.
r _{1,2} the min:	0.

Shoulder gear and chamfer size
mm

d _a the min:	4.6
D _a the max:	8.4
r _a the max:	0.1

Calculation coefficient

k_r :	0.015
f_0 :	10