



Model: 32008XR/QVA621

Basic size of
mm

d:	40
D:	68
T:	19

The basic rated load is
kN

trends C:	60
static state Co:	71
Fatigue load limit	7.65
Pu:	

Rated rotation speed is
r/min

Refer to the speed:	7500
limit speed:	9500
quality:	0.27
model:	*32008XR/QVA621

Dimensions are
mm

d:	40
d ₁ ~ :	54.2
D1:	72
B:	19
C:	14.5
C1:	3.5
r _{1,2} the min:	1
r _{3,4} the min:	1
a:	15

Shoulder gear and chamfer size
mm

d _a the max:	46
d _b the min:	46
r _a the max:	1

Calculation coefficient

e: 0.37

Y: 1.6

Yo: 0.9